

Using a Multimeter



MUST KNOWS

- 0 MEASURE VOLTAGE IN PARALLEL WITH LOAD
 - 0 MEASURE CURRENT IN SERIES WITH LOAD
 - 0 MEASURE RESISTANCE IN A DEAD CIRCUIT
- SET DIAL TO HIGH RANGE AND COME DOWN