

```
void setup()  
{  
  Serial.begin(9600); // Set the baud rate to 9600  
}
```



COM11



Send

a decimal ASCII Code is => 97
b decimal ASCII Code is => 98
c decimal ASCII Code is => 99
d decimal ASCII Code is => 100
e decimal ASCII Code is => 101
f decimal ASCII Code is => 102
g decimal ASCII Code is => 103
h decimal ASCII Code is => 104
i decimal ASCII Code is => 105
j decimal ASCII Code is => 106
k decimal ASCII Code is => 107
l decimal ASCII Code is => 108
m decimal ASCII Code is => 109
n decimal ASCII Code is => 110
o decimal ASCII Code is => 111
p decimal ASCII Code is => 112

☒ Autoscroll ☐ Show timestamp

No line ending ▼

9600 baud ▼

Clear output

1

Arduino/Genuino Uno on COM11