


All models except 140

Check that steering gear bolts (7) are tight.
Torque to 70 Nm using special tool
001 589 66 21 00, if necessary.

Note:

Do not loosen bolts to check torque.
If the torque required to turn the bolt **further** is
less than specified, tighten bolt accordingly.



Special tools

7 Steering gear bolts

