



к преобразователю напряжения					
X(U1).4		602604		→⇨	
1	1.5	Кр	30021	1	1
2	1.5	Кч	31318	1	1
3	2.5	Рз	75301	1	1
4	0.5	Рз	75501	1	1



к жгуту основному					
X8-392.4		929505-1		→⇨	
1	1.5	Кр	30021	1	7
2	1.5	Кч	31318	1	7
3	2.5	Рз	75301	1	7
4	0.5	Рз	75501	1	9