


п. 5


к жгуту дополнительному					
	X9-203.6		1-1418469-1		↔
1	0.75	Кр	30064.	1	5, 15
2	0.75	Ор	15065.	1	5, 15
3	0.75	Кч	31064.	1	5, 15
4	0.75	Жл	60511.	1	5, 15
5	0.75	Зл	60513.	1	5, 15
6					7

Витая пара



A

Адаптер



Трубка гофрированная

Переходник

3
5
7
9
15

29

NW 7.5
L=1700

A


17

п. 6

13

1
5
7
11
15

Витая пара



к блоку TPMS					
X(A29).8		1-1418479-1		↔	
1	0.75	Зл	60513.	1	5, 15
2	0.75	Жл	60511.	1	5, 15
3					7
4					7
5					7
6	0.75	Ор	15065.	1	5, 15
7	0.75	Кр	30064.	1	5, 15
8	0.75	Кч	31064.	1	5, 15

19
21
23
25
27