

Error Message	Error Contents
001-360 Reboot Printer	<IOT Fan Motor Failure> Fan Motor (REAR/FRONT) Failure is detected.
003-340 Resboot Printer	<IOT Firm ware Error> Firm ware Error is detected.
003-356 Reboot Printer	<IOT NV RAM Error> NVRAM Error is detected.
004-310 Reboot Printer	<IOT-Option Feeder Communication Error> Option Feeder Communication Error is detected.
006-370 Reboot Printer	<IOT ROS Motor Failure> The SOS signal does not come from the ROS ASSY.
007-342 Reboot Printer	<IOT Motor Failure> Motor Failure is detected.(MAIN/DEVE/ FUSER)
009-340 Reboot Printer	<IOT CTD Sensor Error> CTD Sensor Error is detected.
009-342 Reboot Printer	<IOT Low Density> Low density is detected.
009-360 Reboot Printer	<IOT (Y) Toner CRUM Error> Yellow Toner CRUM Communication Error is detected.
009-361 Reboot Printer	<IOT (M) Toner CRUM Error> Magenta Toner CRUM Communication Error is detected.
009-362 Reboot Printer	<IOT (C) Toner CRUM Error> Cyan Toner CRUM Communication Error is detected.
009-363 Reboot Printer	<IOT (K) Toner CRUM Error> Black Toner CRUM Communication Error is detected.
Drum Cartridge Error 009-366	<IOT (PHD) CRUM ID Error> PHD(Drum Cartridge) CRUM ID error is detected.
Cyan Cartridge Error 009-367	<IOT (C) Toner CRUM ID Error> Cyan toner CRUM ID error is detected.
Magenta Cartridge Error 009-368	<IOT (M) Toner CRUM ID Error> Magenta toner CRUM error is detected.
Yellow Cartridge Error 009-369	<IOT (Y) Toner CRUM ID Error> Yellow toner CRUM ID error is detected.
Black Cartridge Error 009-370	<IOT (K) Toner CRUM ID Error> Black toner CRUM ID error is detected.
Drum Cartridge Error 009-372	<IOT PHD Type Error> PHD(Drum Cartridge) type error is detected.
Cyan Cartridge Error 009-373	<IOT (C) Toner Type Error> Toner Type Error is detected.
Magenta Cartridge Error 009-374	<IOT (M) Toner Type Error> Toner Type Error is detected.
Yellow Cartridge Error 009-375	<IOT (Y) Toner Type Error> Toner Type Error is detected.
Black Cartridge Error 009-376	<IOT (K) Toner Type Error> Toner Type Error is detected.
Please Request Parts 009-378	<IOT (M) Deve Life Over> Magenta Deve life over is detected.
Please Request Parts 009-379	<IOT (Y) Deve Life Over> Yellow Deve life over is detected.
Please Request Parts 009-380	<IOT (K) Deve Life Over> Black Deve life over is detected.
ZZZ Replace 009-400 ZZZ: printer status	<IOT (C) Deve Life warning> Cyan Deve life warning is detected.
ZZZ Replace 009-401	<IOT (M) Deve Life warning> Magenta Deve life warning is detected.
ZZZ Replace 009-402	<IOT (Y) Deve Life warning> Yellow Deve life warning is detected.
ZZZ Replace 009-403	<IOT (K) Deve Life warning>